SUBJECT:	Cong: Detector Ins	ressional 1 tallation	Notific	ation	- Leak	Damage a	ınd
		(08 Aug.	2007) C	FO 110	6-07		
Distribut		•					
Orig -	Chairman Reyes	HPSCI					
Orig -	Mr. Hoekstra, H	HPSCI		1			
Orig -	Chairman Rocket	eller, sso	CI	J			
Orig -	VChairman Bond,	SSCI					
Orig -	Chairman Murtha	A, HAC/D					
Orig -	Chairman Inouye	e, SAC/D					
1 - :	Mr. Andrew Hire	e, OMB			- · · · · · ·	/ED FOR F 12-07-2010	RELEASE (
1 - 1	DAC						
1 - :	DAC/CFO File						
	ADDCIA Chrono						
1 - 1	D/DS						
1 - 0	C/DS/SCP						
1 - 1	DS Ref						
1 - 1	DS Ref						
1 - 0	CFO						
1 - 1						-	
1 - 1	D/Comptoller						
	CFO/Legal						
	C/COMPT/TA						
	D/OCA/EA						
1 - (	DCA/Liaison						

1 - CFO/COMPT - 2007 Notification Reference File

1 - C/ODNI/RMO 1 - ODNI/CAG

1 - CFO Chrono/FO

SECRET/	//20320713
_	



28 August 2007

The Honorable Silvestre Reyes Chairman Permanent Select Committee on Intelligence House of Representatives Washington, D.C. 20515

Dear Mr. Chairman:
The purpose of this letter is to inform you that the Central Intelligence Agency intends to request that the Office of Management and Budget release from the Fiscal Year (FY) 2007/2008 Reserve for Contingencies to remediate damage to the Building caused by a leaking chilled water loop on the fourth floor and to install leak detectors in the most sensitive Agency computer rooms served by chilled water systems
The leak occurred inside the Building between late afternoon on Friday, July 6, 2007 and early on Saturday, July 7, 2007. By the time the leak was discovered, the central section of the building was affected from the fourth to the second floors. The source of the leak was traced to the filter in the chilled water system.
The third and second floors sustained the most damage; ceiling tiles, cubicle panels, computers, and floor tiles in roughly work areas require replacement. Many of the ceiling tiles in the first floor gym and lobby are also damaged beyond repair.

/20320713

SCRET/

\	
SECRET/	//20320713
\	

The Honorable Silvestre Reyes

prevented or mitigated Building. Accordingly	overed the leak sooner, I the damage to the y, we plan to install le citical computer rooms i	eak detection
Metropolitan Area that will allow us to ident immediately after they	use chilled water syst ify leaks in those faci begin, which would not	tems. Detectors llities almost conly minimize
prevent potentially ca	's infrastructure, but tastrophic interruption	more critically, to our mission.
Reserve for Contingenc	requesting that funds be lies because funds are n 07 budget to cover thes	ot otherwise
Republican Member of Intelligence, the Cha Select Committee on I Appropriations Subcom	identical letters to the House Permanent Selirman and Vice Chairman atelligence, the Chairm mittee on Defense, and Subcommittee on Defens	ect Committee on of the Senate an of the House the Chairman of the
Please do no further assistance.	t hesitate to call me i	f I may be of
	1	* * .
	Sincerely	
	Michael T Merrell	

Michael J. Morrell Associate Deputy Director





Washington, D.C. 20505

28 August 2007

The Honorable Peter Hoekstra
Ranking Republican Member
Permanent Select Committee
on Intelligence
House of Representatives
Washington, D.C. 20515

Dear Mr. Hoekstra:
The purpose of this letter is to inform you that the Central Intelligence Agency intends to request that the Office of Management and Budget release from the Fiscal Year (FY) 2007/2008 Reserve for Contingencies to remediate damage to the Building caused by a leaking chilled water loop on the fourth floor and to install leak detectors in the most sensitive Agency computer rooms served by chilled water systems
The leak occurred inside the Building between late afternoon on Friday, July 6, 2007 and early on Saturday, July 7, 2007. By the time the leak was discovered, the central section of the building was affected from the fourth to the second floors. The source of the leak was traced to the filter in the chilled water system.
The third and second floors sustained the most damage; ceiling tiles, cubicle panels, computers, and floor tiles in roughly work areas require replacement. Many of the ceiling tiles in the first floor gym and lobby are also damaged beyond repair.
SECRET// //20320713

SECRET/	//20320713

The Honorable Peter Hoekstra

$\cdot$
Had we discovered the leak sooner, we could have prevented or mitigated the damage to the Building. Accordingly, we plan to install leak detection systems in our most critical computer rooms in the Washington Metropolitan Area that use chilled water systems. Detectors will allow us to identify leaks in those facilities almost immediately after they begin, which would not only minimize damage to the facility's infrastructure, but more critically, prevent potentially catastrophic interruption to our mission.
We are requesting that funds be released from the
Reserve for Contingencies because funds are not otherwise
available in our FY 2007 budget to cover these unanticipated
developments.
I am sending identical letters to the Chairman of the House Permanent Select Committee on Intelligence, the Chairman and Vice Chairman of the Senate Select Committee on Intelligence, the Chairman of the House Appropriations Subcommittee on Defense, and the Chairman of the Senate Appropriations Subcommittee on Defense.
Please do not hesitate to call me if I may be of
further assistance.
Sincerely,
Michael J. Morrell

SECRET////20320713

Associate Deputy Director

SECRET/		//20320713
---------	--	------------



28 August 2007

The Honorable John D. Rockefeller IV Chairman Select Committee on Intelligence United States Senate Washington, D.C. 20510

The purpose of this letter is to inform you that the Central Intelligence Agency intends to request that the Office of Management and Budget release from the Fiscal Year (FY) 2007/2008 Reserve for Contingencies to remediate damage to the Building caused by a leaking chilled water loop on the fourth floor and to install leak detectors in the most sensitive Agency computer rooms served by chilled water systems Building between late afternoon on Friday, July 6, 2007 and early on Saturday, July 7, 2007. By the time the leak was discovered, the central section of the building was affected from the fourth to the second floors. The source of the leak was traced to the filter in the chilled water system	Dear Chairman Rockefeller:
The leak occurred inside the Building between ate afternoon on Friday, July 6, 2007 and early on Saturday, July 7, 2007. By the time the leak was discovered, the central section of the building was affected from the fourth to the second floors. The source of the leak was traced to the	the Central Intelligence Agency intends to request that the  Office of Management and Budget release from the  Fiscal Year (FY) 2007/2008 Reserve for Contingencies to  remediate damage to the Building caused by a  leaking chilled water loop on the fourth floor and  to install leak detectors in the most sensitive Agency computer
21 Cite Chilited water System.	The leak occurred inside the Building between ate afternoon on Friday, July 6, 2007 and early on Saturday, July 7, 2007. By the time the leak was discovered, the central section of the building was affected from the fourth
The third and second floors sustained the most damage; ceiling tiles, cubicle panels, computers, and floor tiles in roughly work areas require replacement. Many of the ceiling tiles in the first floor gym and lobby are also damaged beyond repair.	ceiling tiles, cubicle panels, computers, and floor tiles in roughly work areas require replacement. Many of the ceiling tiles in the first floor gym and lobby are also damaged beyond

/20320713

SECRET/	/20320713

The Honorable John D. Rockefeller IV

Had we discovered the leak sooner, we could have prevented or mitigated the damage to the Building. Accordingly, we plan to install leak detection systems in our most critical computer rooms in the Washington Metropolitan Area that use chilled water systems. Detectors will allow us to identify leaks in those facilities almost immediately after they begin, which would not only minimize damage to the facility's infrastructure, but more critically, prevent potentially catastrophic interruption to our mission.
We are requesting that funds be released from the
Reserve for Contingencies because funds are not otherwise
available in our FY 2007 budget to cover these unanticipated
developments.
I am sending identical letters to the Vice Chairman of the Senate Select Committee on Intelligence, the Chairman and Ranking Republican Member of the House Permanent Select Committee on Intelligence, the Chairman of the House Appropriations Subcommittee on Defense, and the Chairman of the Senate Appropriations Subcommittee on Defense.
Please do not hesitate to call me if I may be of further assistance.
Gingonoly
Sincerely,
Michael J. Morrell
MOCCHAEL V. MULLELL

SECRET/ /20320713

Associate Deputy Director

1	
SECRET/	//20320713



28 August 2007

The Honorable Christopher S. "Kit" Bond Vice Chairman Select Committee on Intelligence United States Senate Washington, D.C. 20510

Dear Vice Chairman Bond:
The purpose of this letter is to inform you that the Central Intelligence Agency intends to request that the Office of Management and Budget release from the Fiscal Year (FY) 2007/2008 Reserve for Contingencies to remediate damage to the Building caused by a leaking chilled water loop on the fourth floor and to install leak detectors in the most sensitive Agency computer rooms served by chilled water systems .
The leak occurred inside the Building between rate afternoon on Friday, July 6, 2007 and early on Saturday, July 7, 2007. By the time the leak was discovered, the central section of the building was affected from the fourth to the second floors. The source of the leak was traced to the filter in the chilled water system.
The third and second floors sustained the most damage; ceiling tiles, cubicle panels, computers, and floor tiles in roughly work areas require replacement. Many of the ceiling tiles in the first floor gym and lobby are also damaged beyond repair.
<b>\</b>

\_\_\_/20320713

The Honorable Christopher S. "Kit" Bond

Had we discovered the leak sooner, we could have prevented or mitigated the damage to the Building. Accordingly, we plan to install leak detection systems in our most critical computer rooms in the Washington Metropolitan Area that use chilled water systems. Detectors will allow us to identify leaks in those facilities almost immediately after they begin, which would not only minimize damage to the facility's infrastructure, but more critically, prevent potentially catastrophic interruption to our mission.  We are requesting that funds be released from the Reserve for Contingencies because funds are not otherwise
available in our FY 2007 budget to cover these unanticipated developments.
acverophienes.
I am sending identical letters to the Chairman of the Senate Select Committee on Intelligence, the Chairman and Ranking Republican Member of the House Permanent Select Committee on Intelligence, the Chairman of the House Appropriations Subcommittee on Defense, and the Chairman of the Senate Appropriations Subcommittee on Defense.
lease do not hesitate to call me if I may be of furt istance.
· · · · · · · · · · · · · · · · · · ·
Sincerely

Michael J. Morrell Associate Deputy Director

SECRET/	/20320713
SECUEIV	/20320/13



Washington, D.C. 20505

28 August 2007

The Honorable John P. Murtha Chairman
Subcommittee on Defense
Committee on Appropriations
House of Representatives
Washington, D.C. 20515

Dear Mr. Chairman:
The purpose of this letter is to inform you that the Central Intelligence Agency intends to request that the Office of Management and Budget release from the Fiscal Year (FY) 2007/2008 Reserve for Contingencies to remediate damage to the Building caused by a leaking chilled water loop on the fourth floor and to install leak detectors in the most sensitive Agency computer rooms served by chilled water systems.
The leak occurred inside the Building between late afternoon on Friday, July 6, 2007 and early on Saturday, July 7, 2007. By the time the leak was discovered, the central section of the building was affected from the fourth to the second floors. The source of the leak was traced to the filter in the chilled water system.
The third and second floors sustained the most damage; ceiling tiles, cubicle panels, computers, and floor tiles in roughly work areas require replacement. Many of the ceiling tiles in the first floor gym and lobby are also damaged beyond repair.

SECRET//	/20320713
-	

The Honorable John P. Murtha

Had we discovered the leak sooner, we could have prevented or mitigated the damage to the Building. Accordingly, we plan to install leak detection systems in our most critical computer rooms in the Washington Metropolitan Area that use chilled water systems. Detectors will allow us to identify leaks in those facilities almost immediately after they begin, which would not only minimize damage to the facility's infrastructure, but more critically, prevent potentially catastrophic interruption to our mission.
We are requesting that funds be released from the Reserve for Contingencies because funds are not otherwise available in our FY 2007 budget to cover these unanticipated developments.
() I am sending identical letters to the Chairman and Ranking Republican Member of the House Permanent Select Committee on Intelligence, the Chairman of the Senate Appropriations Subcommittee on Defense, and the Chairman and Vice Chairman of the Senate Select Committee on Intelligence.
Please do not hesitate to call me if I may be of further assistance.
Sincerely

Michael J. Morrell Associate Deputy Director





28 August 2007

The Honorable Daniel K. Inouye Chairman
Subcommittee on Defense
Committee on Appropriations
United States Senate
Washington, D.C. 20510

Dear Chairman Inouye:
The purpose of this letter is to inform you that the Central Intelligence Agency intends to request that the Office of Management and Budget release from the Fiscal Year (FY) 2007/2008 Reserve for Contingencies to remediate damage to the Building caused by a leaking chilled water loop on the fourth floor and to install leak detectors in the most sensitive Agency computer rooms served by chilled water systems
The leak occurred inside the
The third and second floors sustained the most damage; ceiling tiles, cubicle panels, computers, and floor tiles in roughly work areas require replacement. Many of the ceiling tiles in the first floor gym and lobby are also damaged beyond repair.
SECHET/ /20320713

SECRET/	/20320713
\	

The Honorable Daniel K. Inouye

Had we discovered the leak sooner, we could have prevented or mitigated the damage to the Building. Accordingly, we plan to install leak detection systems in our most critical computer rooms in the Washington Metropolitan Area that use chilled water systems. Detectors will allow us to identify leaks in those facilities almost immediately after they begin, which would not only minimize damage to the facility's infrastructure, but more critically, prevent potentially catastrophic interruption to our mission.
We are requesting that funds be released from the Reserve for Contingencies because funds are not otherwise available in our FY 2007 budget to cover these unanticipated developments.
I am sending identical letters to the Chairman and Ranking Republican Member of the House Permanent Select Committee on Intelligence, the Chairman of the House Appropriations Subcommittee on Defense, and the Chairman and Vice Chairman of the Senate Select Committee on Intelligence.
Please do not hesitate to call me if I may be of
further assistance.
Sincerely,
Michael J. Morrell

SECRET/ /20320713

Associate Deputy Director